

S/N: 024900-4

250 250 250

251		250
-----	--	-----

A hand-drawn circular diagram representing a vaulted dome. The diagram is divided into two main sections by a horizontal line. The upper section contains several points labeled with numbers: 219, 221, 234, 229, 253, 245, 251, 250, 247, 243, 231, 244, 247, 250, 247, 247, 234, 246, 246, 253. The lower section contains points labeled: 236, 249, 248, 247, 248, 243, 250, 256, 250. A semi-circular area at the bottom is labeled 'Vault'.

ADD Ground Cable
Replace Broken Gauge BOARD
Tank in Good Overall Condition For A 5YR Turnaround.

Date: August 11, 2019

Date: 03/09/2019

Type of Inspection: VT Rev: 3.0

Test Technique: UT thickness(4.2)

Equipment: DMS 2/ Flashlight/ grinder

Code/Standard: client information

Client: HUSKY OIL OPERATIONS

IRISNDT #: LYN1901317

Location: 111/ 4-34-48-27 W3M, SK

Item Inspected: 1000bbl TANK S/N# 024900-4



Date: 2019-Aug-11

WO #: 81416259

PO #: 8401361402

A UT and Visual inspection was carried out as requested on 1000bbl tank, refer to attached pages for additional information

1000bbl Tank S/N# 024900-4 : replace broken gauge board, add grounding cable. the tank is in good overall condition for a 5yr turnaround.




Requested by Dave Miller

Approver : Jesse Schlosser 2Z-02006778

DMS 2 S/N# SCA2097 CAL DATE: JAN 9.2019

F2HE PROBE S/N# SCA2097

Inspection Limitation(s): Oil deposits on the shell and piping, rusty floor. first course cleaned for inspection

Unit#: <u>767</u> Kilometers: _____ In: _____ Out: _____ Hrs: _____ In: _____ Out: _____ Hrs: _____ Personnel: STEPHEN BRYAN / BRADY HARVEY	Consumables: MIN	Interpretation by: Stephen Bryan (Print) _____ (Sign)  Client Representative: Terry Neufeld (Print) _____ I am in full agreement with report contents (Sign) _____	SNT-TC-1A: _____ C.G.S.B.: <u>12459</u> (Level) C.G.S.B #: _____
---	---------------------	--	---

5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873

Calgary (403) 279-6121

Lloydminster (780) 875-6455

Barrhead (780) 674-3018

Nisku (780) 955-7616

Cold Lake

Fort McMurray

Red Deer

(780) 826-6105

(780) 743-1536

(403) 347-1742

www.irisndt.com

Engineering, Calgary

Engineering, Edmonton


Rope Access Services

Offices also located in USA and UK

(403) 217-9684

(780) 437-2022

(780) 437-2022



Replace broken gauge board

IRISNDT #: LYN1901317

Date: 2019-Aug-11

Stephen Bryan

(Print)

Client: HUSKY OIL OPERATIONS

(Sign)

5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873
 Calgary (403) 279-6121
 Lloydminster (780) 875-6455
 Barrhead (780) 674-3018
 Nisku (780) 955-7616

Cold Lake
 Fort McMurray
 Red Deer

(780) 826-6105
 (780) 743-1536
 (403) 347-1742

www.irisndt.com

Engineering, Calgary
 Engineering, Edmonton
 Rope Access Services
 Offices also located in USA and UK

(403) 217-9684
 (780) 437-2022
 (780) 437-2022