

- ① AIRIEL 4 $\frac{1}{4}$ " CLASS HJ MAWP 2600  
 VVCP S/N C-65751 REBUILT READY TO RUN BORE 4.259
- ② AIRIEL 4 $\frac{1}{4}$ " CLASS HJ MAWP 2600  
 VVCP S/N C-67630 REBUILT READY TO RUN BORE 4.285
- ③ IR 6" RDS MAWP 1650  
 NO VVCP S/N Y6R1436C READY TO RUN BORE 4.250
- ④ IR 9 $\frac{1}{2}$ " RDS MAWP 1000  
 VVCP S/N Y6R857-C READY TO RUN BORE 4.285
- ⑤ IR 11 $\frac{1}{2}$ " RDS MAWP 605  
 NO VVCP S/N Y6R1439C READY TO RUN BORE 4.250
- ⑥ IR 13 $\frac{1}{2}$ " RDS MAWP 210  
 VVCP S/N Y6R5028C NEEDS REBUILD BORE 4.250
- ⑦ IR 18" RDS MAWP 180  
 NO VVCP S/N Y5R-183 HAVE NEW SET OF HUBRIGER STEEL VALVES FOR IT