62051553

IRISNDT

NONDESTRUCTIVE INSPECTION REPORT

SB382-NDT-336

Type of Inspection: UT/ VT	**Client:** HUSKY OPERATIONS	**Date:** 28-Jul-15
Test Technique: UT THICKNESS	**IRISNDT #:** LYD1500753	**WO #:** 81025212
Equipment: DMS2/ GRINDER/ SPOTLIGHT	**Location:** A9-7-46-25 W3M, SK	**PO #:** 8400982837
Code: CLIENT SPECS/ CLIENT INFO	**Item Inspected:** 1000 BBL TANK S/N# 03.09.24.12534	

Inspection Results: a UT and visual inspection was carried out as requested on a 1000bbl tank , refer to attached pages for inspection results.

REQ: KYLE FORBES

APP: KYLE FORBES 2Z-02017604

Unit#: 767 Kilometers: 60

In: 0700 Out: 0900 Hrs: 2.0

In: Out: Hrs:

Personnel:
STEPHEN BRYAN / LOGAN SKINNER

Consumables:
2 GAS MONITORS

Interpretation by:

STEPHEN BRYAN (Print) SNT-TC-1A: 2

C.G.S.B.: 2 (Level)

(Signature) C.G.S.B. #: 12459

Client Representative: (Print)

I am in full agreement with report contents (Sign)

5311 - 86 Street, Edmonton, Alberta T6E 5T8 Phone: (780) 437-2022 fax: (780) 436-4873

Calgary (403) 279-6121
Lloydminster (780) 875-6455
Barrhead (780) 674-3018
Nisku (780) 955-7616
Cold Lake (780) 826-6105
Fort McMurray (780) 743-1536
Red Deer (403) 347-1742
www.irisndt.com
Engineering, Calgary (403) 217-9684
Engineering, Edmonton (780) 437-2022
Rope Access Services (780) 437-2022
Offices also located in USA and UK